ENCL

Rocky Flats Area Office

CORPES CONTROL INCOMING LTR NO

DIST SANCHINI, D.J.

BADER, C.P

MCNETT, J.F

SMITH, R.E. WEIDNER, C.W WESTON, W.F.

WILSON, G.L

YOUNG, E.R.

WOZNIAK, B.O.

BETCHER, D.H.

CAPNIVAL GU

JARMAN, L.K. HEBERT, J.L.

HOEY, J.B

KRIEG, D.M. LIM, B.W.

NAIMON, E.R.

POTTER, G.L ROECKER, J.H

LOUDENBURG, G.E.

VELASQUEZ, R.N. WICKLAND C.E.

MEYERS, G.W SHANNON, W.M.

CAMPBELL, G.W. HOOD, R.C KINZER, J.E. KIRBY, W.A.

emorandum

Albuquerque Operations Office



000025179

GCT 1 9 1997

S&E:JWK F:

Immobilization of Residual Solar Evaporation Pond Sludge Τ:

William F. Weston Director, Plutonium Operations Rockwell International, NASO, RFP

As part of the on-going Solar Evaporation Pond closure activities, Rockwell is currently engaged in removal of water for treatment as process wastewater, and removal of sludge for immobilization in a concrete matrix. As the water level recedes in the ponds, residual sludge is exposed to the atmosphere. Rockwell personnel are currently washing the sludge back into the pond on a daily basis, however, some residue remains.

The Area Office is concerned about the potential for resuspension of particulate matter from the solar ponds and has expressed this concern verbally to Rockwell RCRA/CERCLA Program personnel. Kirk McKinley, RCRA/ CERCLA Program Manager, has proposed the application of a dust suppressor to the residue in order to prevent this potential resuspension. We support this preventive measure, but expect Rockwell personnel to prove its effectiveness. Therefore, the Area Office requests that radiation monitoring smear areas of visible residue weekly as a confirmation that the dust suppressor is effectively immobilizing any sludge residues. Additionally, radiation monitors should smear the area prior to the application of dust suppressor to confirm the need for such a treatment.

Please document activities taken to immobilize any residual Solar Evaporation Pond sludge, including radiation monitoring results, and present the data to John Krueger of my staff beginning October 26, 1987

Ronald D. Reed, Chief

Safety and Environmental Branch

J. B. Whitsett, RFAO

G. W. Campbell, Rockwell

Received for Addressee Carres, Control RFF

Aer Lir s

admin reccrd 1101-A-00053 000053

aa wayo Buur ya